

U. S. Department of Agriculture

FOREST SERVICE

S. O.

H/2

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 30 5 Mer.

SE 1/16 Corner common to Sections

9, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a 1" iron pipe w/brass cap. ~~rock~~ in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|  |    |        |  |
|--|----|--------|--|
|  | No | B. Ts. |  |
|  |    |        |  |

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*H. E. Altman*

H. E. ALTMAN

(Signature)

Assistant Ranger

5/23/36


(Date)

(Title)

Metal Location Poster is on a \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.

Corner is located at fence corner.



(Make sketch of topography near Corner)