

U. S. Department of Agriculture
FOREST SERVICE

Posted *N13*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *30 W* *5th* Mer.

Sec Corner common to Sections
16, 15, 21, and 22



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SEC 15

SEC 21

B.T.

B.T.

Species *N. Pine (stump 18" high)* *N. Pine (stump)*

Diameter *20"* *14"*

Bearing *N(?) E* *S(?) W*

Distance *56* *50'*

Do you believe this to be a genuine Land Office Corner? *X*

If not, why? _____

H. M. Anderson

(Signature)

ENGINEER

(Title)

3/18/35

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *NONE*



(Make sketch of topography near Corner)

T. 141N R. 30W

5

N-13 Mer.