

U. S. Department of Agriculture
FOREST SERVICE

123
7-29-37
[Handwritten initials]

K13

Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5th Mer.

N 1/4 Corner common to Sections

....., 15, and 16

Corner consists of a 1" I.P. w/ brass cap (not) in place


State condition Good

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland
(Signature)

Const. For
(Title)

Nov. 17, 1936
(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant. 028

from which this Corner bears 699E

side of

tree 5 inches diameter, on the

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 14 N. R. 30 W.

6-7 K-13

MEP.