

U. S. Department of Agriculture
FOREST SERVICE

123
7-29-39
PP

Chippewa NATIONAL FOREST J 13

CORNERS OF THE PUBLIC SURVEY

T. 14 N. R. 30 W. 5th Mer.

Corner common to Sections

9, 10, 15, and 16

Corner consists of a 2" I.P.W/brass cap (not) in place


State condition Good

Dimensions above ground 1 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

Const. Eng.

(Title)

Nov. 13, 1936
(Date)

Corner again.

Give any further facts which will aid in finding this


old chains distant.

from which this Corner bears *N 11 W*

side of

tree *6* inches diameter, on the

Metal Location Poster is on a *Jack Pine*



(Make sketch of topography near Corner)

T. L. H. N. R. 30 W

5th T-13