

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

EB

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 30W 5<sup>th</sup> Mer.

Section Corner common to Sections

3, 4, 9, and 10

Corner consists of a Not located (not) in place  
State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T141N  
R30W  
S3

BT

Species Aspen

Diameter 1 1/2

Bearing NE

Distance 1/2 ch.

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

Dorman J. Sutton

(Signature)

Engineer

(Title)

3-6-35  
(Date)

Corner again:

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *SW*

side of *tree*

tree *12* inches diameter, on the *south*

Metal Location Poster is on an *Aspen*



(Make sketch of topography near Corner)

*T. 141 N.*

*R. 30 W.*

*S. 14*

Mer.

*E-13*