

U. S. Department of Agriculture  
FOREST SERVICE

123  
73837  
E14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5th Mer.

W 1/6 Corner common to Sections

3, and 10

Corner consists of a point on Hy. #34 (not) in place  
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

Approximate location of  
L. L. O.


Carl Steadland  
(Signature)

Const. Far.  
(Title)

Nov. 12, 1936  
(Date)

Metal Location Poster is on a *Nack Pine* tree *10* inches diameter, on the side of *SW E* from which this Corner bears *1.00* chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 141 N. R. 30 W. S. 4 E-14 Mer.