

U. S. Department of Agriculture
FOREST SERVICE

173
7-31-37
[Signature]

Chippewa NATIONAL FOREST D14

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 30 W 5th Mer.

SW 1/4 Corner common to Sections

3, _____, and _____

Corner consists of a 1" I.P. w/ brass cap (not) in place



State condition Good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadman
(Signature)

Nov. 12, 1936
(Date)

Const. Forester
(Title)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears *N 2 W*

side of

tree *8* inches diameter, on the

Metal Location Poster is on a *Cedar*



(Make sketch of topography near Corner)

T. 141 N. R. 30 W

S. 4 Mer. D-14