

U. S. Department of Agriculture  
FOREST SERVICE

122  
7-29-37  
[Signature]

Chippewa NATIONAL FOREST

615

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 30W 5th Mer.

C 1/2

Corner common to Sections

10, \_\_\_\_\_, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a 1" I.P. w/ brass cap (set) in place


State condition Good

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Carl Steadland

(Signature)


Const. For

(Title)

Nov. 10, 1936  
(Date)

Metal Location Poster is on a *Nor. Face* side of tree *H* inches diameter, on the from which this Corner bears *N 33 E* chains distant. *0.10*

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 141N R. 30W  
 5-4  
 6-15  
 MGT.