

U. S. Department of Agriculture
FOREST SERVICE

123
7-29-37
[Signature]

Chippewa NATIONAL FOREST F15
CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 30 W. 5th Mer.

CN 1/4 Corner common to Sections
10, and



Corner consists of a 1" I.P. U/brass cap (lost) in place
State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? _____

Carl Steadland
(Signature)

Const. Eng.
(Title)

Nov. 10, 1936
(Date)

Corner again.
 Give any further facts which will aid in finding this
 chains distant. *0.26*
 from which this Corner bears *N 74 E*
 side of
 tree *←* inches diameter, on the
 Metal Location Poster is on a *Nor. Pine*



(Make sketch of topography near Corner)

T. 141 N. R. 30 W.
54
 Mer. **F-15**