

123  
7-29-37  
*[Signature]*

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST H 16

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5<sup>th</sup> Mer.

SE 1/16

Corner common to Sections

10, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a 1" I.P.W. brass cap (not) in place


State condition Good

Dimensions above ground 7 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_


Carl Steadland

(Signature)

Nov. 12, 1936  
(Date)

Constr. For.  
(Title)

Corner again.  
 Give any further facts which will aid in finding this  
 from which this Corner bears *0.20* chains distant.  
*5.995*  
 side of  
 tree *11* inches diameter, on the  
 Metal Location Poster is on a *Lock Pine*



(Make sketch of topography near Corner)

T. 141 N. R. 30 W. 574 H-16 Mer.