

U. S. Department of Agriculture
FOREST SERVICE

1237
7-219-37
G 16
R

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *141 N.* R. *30 W* *5th* Mer.

CE 1/4 Corner common to Sections
10, _____, and _____



Corner consists of a *1" I.P. brass cap (not)* in place
State condition *Good*

Dimensions above ground *3"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadley

(Signature)

Nov. 12, 1936
(Date)

Constr. For
(Title)

Faint, illegible text on the top half of the page, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this


chain distant. 0.11

from which this Corner bears 595 W

side of

tree 5 inches diameter, on the

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. H. N. R. 30W
674
G-16
Met.