

U. S. Department of Agriculture  
FOREST SERVICE

*Copied  
Booked  
5/34*

*N19*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 30 Mer.

1/4

Corner common to Sections

14, and 23

Corner consists of a 1" iron pipe (~~30~~) in place

State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<b>NONE</b>			
N	W	S	E

<b>NONE</b>			
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<b>NONE</b>		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*H. E. Altman*  
**H. E. ALTMAN**

(Signature)

**Jr. Forester**

(Title)

**3/30/36**

(Date)


Old fence runs E and W south of corner  
Corner again.

Give any further facts which will aid in finding this  
chains distant.

from which this corner bears  
N 28° W

side of  
tree 7  
inches diameter, on the west

Metal Location Poster is on a  
Burr Oak



(Make sketch of topography near corner)