

U. S. Department of Agriculture
FOREST SERVICE

123
7-21-37
616
R

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 30 W 5th Mer.

CE 1/4 Corner common to Sections
10, _____, and _____



Corner consists of a 1" I.P.W/brass cap (not) in place
State condition Good

Dimensions above ground 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadley

(Signature)

Nov. 12, 1936

(Date)

Constr. For.

(Title)

[Faint, illegible text on ruled lines]

Corner again.

Give any further facts which will aid in finding this


chains distant. *0.11*

from which this Corner bears *595 W*

side of

tree *5* inches diameter, on the

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. W. R. 30W

Mer. G-16 574