

U. S. Department of Agriculture
FOREST SERVICE

S.O.

A-334 ✓

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141-142 R. 30 5 Mer.

1/6 4 (10 ch. W. of E 1/16) Corner common to Sections

31, 6, and

Corner consists of a 1" iron pipe w/ brass cap ~~set~~ in place

State condition Good

Dimensions above ground 1 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | | | | | |
|---|------|---|------|----|----|----|----|
| | AP 4 | | AP 3 | | | | |
| | TR | | TR | | | | |
| | 1213 | | 1327 | | | | |
| N | W | S | E | NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|-------|-----|--|
| | No B. | Ta. | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. E. Altman

H. E. ALTMAN

(Signature)

Assistant Ranger

(Title)

9/14/36

(Date)

cc-8.0.
C.L.H.
7-48


Corner is in center of road bed
with pipe bent so that brass cap rests
on ground with 6" of bent pipe
exposed.

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears
South west
side of
Road
6 inches diameter, on the North
Metal Location Poster is on a Telephone pole



(Make sketch of topography near Corner)

A-3,4
Mer.