

U. S. Department of Agriculture

FOREST SERVICE

E-F15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5th Mer.

1/64 Corner common to Sections 10, located 10 chs. N. of CN 1/4 corner

Corner consists of a 1" I.P.W./brass cap (not) in place



State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


Carl Steadland (Signature)

Const. For. (Title)

Nov. 9, 1936 (Date)

Metal Location Poster is on a *W. Oak* tree *6* inches diameter, on the side of from which this Corner bears *N 48 W* chains distant. *0.09*

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 141N R. 30W
 5th
 E-F-15
 Mer.