

U. S. Department of Agriculture

FOREST SERVICE

EF 160

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5th Mer.

1/4 Corner common to Sections 10, located 10 chs. N. of NE 1/4 corner


Corner consists of a 1" I.P.N. brass cap (not) in place State condition Good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)


Const. Eng.

(Title)

Nov. 12, 1936 (Date)

Lined writing area with two punch holes at the top.

Corner again.
Give any further facts which will aid in finding this
chains distant.
0.22
from which this Corner bears
side of
tree 8 inches diameter, on the
Metal Location Poster is on a
Vack Pine



(Make sketch of topography near Corner)

T. 141 N. R. 30 W. 5 TA E3F-K Mer.