

U. S. Department of Agriculture  
FOREST SERVICE

*WJA*

*J4-5*

*CHIPPEWA* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *30W* *5th* Mer.

*1/64* Corner common to Sections  
*7*, and *18*

Corner consists of a *2" IRON PIPE, CAP* (not) in place  
State condition *GOOD*

Dimensions above ground *10"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *YES*

If not, why? \_\_\_\_\_

*Arthur J. Johnson*

(Signature)

*Gene Keller*

(Title)

*2/37*  
(Date)

ALONG ROAD

Corner again.

Give any further facts which will aid in finding this

chains distant.


17

from which this Corner bears N. 86° W.

side of

tree 5 inches diameter, on the

Metal Location Poster is on a RED OAK



(Make sketch of topography near Corner)

T. 141

R. 30

57

545