

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31 & 32W 5th Mer.
Section

Corner common to Sections

25, 30, 36, and 31

Corner consists of a cap. iron pipe (not) in place



State condition good

Dimensions above ground 2 1/2 x 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grown
over

Species R. Oak

Diameter 7"

Bearing S 76 1/2 E

Distance 20

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Hubbard Co. Resurvey

Dorman J. Sutton

(Signature)

Engineer

(Title)

3-22-35


(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

From which this Corner bears *N 76 1/2° W*
side of *tree*
tree *7* inches diameter, on the *NW*
Metal Location Poster is on a *R. Oak*



(Make sketch of topography near Corner)

T. 141 N R. 31+32 W 5th Mer.