

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

Y3

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 5th Mer.

~~S. S.~~ 1/16 ¹² Corner common to Sections

, , , and 31

Corner consists of a 1 1/2" Iron pipe (cast) in place

State condition good

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? noIf not, why? Records show it was setby County Surveyor.

Arthur P. Johnson
 Arthur P. Johnson
 (Signature)

Project Ass't

10/10/38

(Date)

(Title)

CP

This corner lies 6 chains east of
old road running south from Moore's
Springs Resort.

Corner again.

Give any further facts which will aid in finding this

10 chains distant.


S22°W

from which this Corner bears

side of

tree 4 inches diameter, on the

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 141 N R. 31 W 5th Mer.