

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *31* Mer. *5*

46 Corner common to Sections *7*, and *18*

Corner consists of a *IRON PIPE* (not) in place
State condition

Dimensions above ground *11* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *SUBDIVIDED BY COUNTY*

Doc Purvis
(Signature)
4/3/35
(Date)
Estimator
(Title)

Corner again.

Give any further facts which will aid in finding this


78 LINKS chains distant.

from which this Corner bears N 18° W

side of CORNER

tree 5 inches diameter, on the SOUTH

Metal Location Poster is on a RED OAK



(Make sketch of topography near Corner)

T 141 R 31 Mer.