

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST *M-5 Top 2*

CORNERS OF THE PUBLIC SURVEY

T. *14 N.* R. *31 W.* *5<sup>th</sup>* Mer.

*S<sup>11</sup>/<sub>16</sub>* Corner common to Sections

*17*, and *18*

Corner consists of a *2<sup>1</sup>/<sub>2</sub>" I.P.* (not) in place

State condition *Good*

Dimensions above ground *12* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species *J.P. J.P.*

Diameter *8 8*

Bearing *S40W N7E*

Distance *0.07 0.03*

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Corner*

*R. Moore*  
(Signature)

*6/16/37*  
(Date)

*Asst. Dir. FHS*  
(Title)

Corner again.

Give any further facts which will aid in finding this


0.07 chains distant.

From which this Corner bears N40E

side of

tree 8 inches diameter, or the

Metal Location Poster is on a *Stone*



(Make sketch of topography near Corner)

M-5

6-74

T. L. N. R. 3110

Mer.

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

CHIPPewa NATIONAL FOREST *M-5 2/2*

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *21 W* *5th* Mer.  
*S 1/6* Corner common to Sections

*17*, and *18*  
Corner consists of a *1 1/2" IRON PIPE* (~~not~~) in place  
State condition *GOOD*

Dimensions above ground *24* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *NO*

If not, why? *APPARENTLY SET BY*  
*COUNTY ENGINEER*

*Arthur J. Johnson*

(Signature)

*Lewis Child Walker*

(Title)

*12/10/37*  
(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

522

R. 31W

T. 141N

M-5

Form 874-0—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Posted

CHIPPENAW NATIONAL FOREST M5

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31W 5th Mer.  
S 1/6 Corner common to Sections

17, and 18  
Corner consists of a 1 1/2" IRON PIPE ( ) in place  
State condition GOOD

Dimensions above ground 24" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? APPARENTLY SET BY COUNTY ENGINEER

*Arthur J. Johnson*  
(Signature)

*Leona Chilled Worker*  
(Title)

12/10/27  
(Date)

Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141N R. 21W 57E Mer.