

Form 874-8—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST

H5

CORNERS OF THE PUBLIC SURVEY

T. *141N* B. *31W* *5th* Mer.

*S 1/2* Corner common to Sections

\_\_\_\_\_, \_\_\_\_\_, *7*, and *8*  
Corner consists of a *2" I.P.* (not) in place


State condition *Good*

Dimensions above ground *10* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Corner*

*Carl E. Steadman*  
(Signature)

*Foreman - F-48*  
(Title)

*6/15/37*  
(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

chains distant. *0.11*


from which this Corner bears *0 42 W*

side of

tree inches diameter, on the

Metal Location Poster is on a *03*

*Copied*



(Make sketch of topography near Corner)

*T. LAIN. R. 31 W*  
*5 1/2 Mer.*

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa* NATIONAL FOREST **H-5** ✓

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *31W* Mer. *52*

*8 1/16* Corner common to Sections *7*, and *8*

Corner consists of a *2" I.P.* (not) in place  
State condition *Good*

Dimensions above ground *10* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Corner*

*Carl H. Steadland*  
(Signature)

*6/15/37*  
(Date)

*Foreman - F48*  
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.11

from which this Corner bears


S 72 W

side of

tree inches diameter, on the

Map

Metal Location Poster is on a



(Make sketch of topography near Corner)

H-5

Mer.

5 21

T. W. H. R. 31 W