

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

CHIPPENAWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31W 5th Mer.
S. W 1/4 Corner common to Sections

-----, -----, and 18
Corner consists of a 1 1/2 Iron pipe (not) in place
State condition Good

Dimensions above ground 16" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? NO

If not, why? APPARENTLY SET BY

COUNTY ENGINEER

Arthur J. Johnson

(Signature)

Semi-Skilled Worker

(Title)

12/10/37
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.	Sec. 18	

(Make sketch of topography near Corner)

T. 141 N. R. 21 W. Mer. *STL*