

U. S. Department of Agriculture

FOREST SERVICE

*Part 13* XFB  
Z13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 31 W. 5th. Mer.

Section \_\_\_\_\_ Corner common to Sections

\_\_\_\_\_, \_\_\_\_\_, 53, and 34

Corner consists of a 2" Iron Pipe ~~(rod)~~ in place

State condition Good

Dimensions above ground 24 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Apparently set by County

Engineer.

*Arthur J. Johnson*  
(Signature)

Semi Skilled Worker

(Title)

2/1/38

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


10 chains distant.

from which this Corner bears S. 40° E.

side of Tree

tree 6 inches diameter, on the Southeast

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. 5th Mer.