

U. S. Department of Agriculture  
FOREST SERVICE

L 13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 514 Mer.

14 Corner common to Sections  
....., ..... 15, and 16.....

Corner consists of a 4" Aspen post (not) in place  
State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ..... is located .....

..... Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species .....

Diameter .....

Bearing .....

Distance .....

Do you believe this to be a genuine Land Office Corner? No

If not, why? .....


Approximate location—  
established by C.C.C. crew

Carl Steadland  
(Signature)

Const. For.  
(Title)

Dec. 23, 1936  
(Date)

Metal Location Poster is on a *Yack Pine* tree *7* inches diameter, on the side of from which this Corner bears *0.24* chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. W. N. R. 31W. 5<sup>th</sup> Mer.