

U. S. Department of Agriculture
FOREST SERVICE

J13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 5th Mer.

----- Corner common to Sections

9, 10, 15, and 16Corner consists of a 3" Aspen post (not) in placeState condition GoodDimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? No

If not, why? -----

Approximate locationEstablished by C.C.C. crewCarl Steadland

(Signature)

Dec. 24, 1936

(Date)

Const. For.

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. *0.10*

from which this Corner bears *S 76° W*

side of

tree *10* inches diameter, on the

Metal Location Poster is on a *Flm*



(Make sketch of topography near Corner)

Mer.

5th

T. 141N. R. 31W.