

U. S. Department of Agriculture
FOREST SERVICE

123
1-29-37
C.C.C.

L-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N R. 31 W 5th Mer.

SW 1/4

Corner common to Sections

15, _____, and _____

Corner consists of a 3" Cedar post (not) in place

State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

Approximate location established by C.C.C. crew.

Carl Steadland

(Signature)

Dec. 24, 1936

(Date)

Const. Foreman

(Title)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


chains distant. *0.77*

from which this Corner bears *5227*

side of

tree *16* inches diameter, on the

Metal Location Poster is on a *Nack Flae*



(Make sketch of topography near Corner)

Mer. 7-14

T. 141 N. R. 31 W. 5th

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

214

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 5th Mer.

CW 1/4 Corner common to Sections
15, _____, and _____

Corner consists of a 3" Cedar post (not) in place
State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

Approximate location

Established by CCC crew

Carl Steadland
(Signature)

Dec 24, 1936
(Date)

Constr. for
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

066


from which this Corner bears

5225

side of

tree *16* inches diameter, on the

Metal Location Poster is on a *back line*



(Make sketch of topography near Corner)

Mer.

5-74

R. 31 W.

T. 14 N.