

U. S. Department of Agriculture  
FOREST SERVICE

123  
7-29-37  
L

L-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 5-75 Mer.

C 1/4 Corner common to Sections  
15, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a 4" Aspen post (not) in place  
State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? \_\_\_\_\_

Approximate location

Established by C.C.C. crew.

Carl Steadland  
(Signature)

Dec. 24, 1936.  
(Date)

Const. Eng.  
(Title)

Dashed lines for writing.

Corner again.

Give any further facts which will aid in finding this


*0.44* chains distant.

from which this Corner bears *N 51 E*

side of

tree *18* inches diameter, on the

Metal Location Poster is on a *Nor Pine*



(Make sketch of topography near Corner)

*L-15*

*T. H. N. R. 31 W.*

Mer.

*57A*

U. S. Department of Agriculture  
FOREST SERVICE

215

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N R. 31 W 5<sup>th</sup> Mer.

C/4

Corner common to Sections

15,

and

Corner consists of a 4" Aspen post (not) in place

State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? \_\_\_\_\_

Approximate location

Established by C.C.C. crew.

Carl Steadland

(Signature)

Const. For.


(Title)

Dec. 24, 1936.

(Date)

Metal Location Poster is on a *Nor. Pine* tree *18* inches diameter, on the side of from which this Corner bears *0.44* chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. S. 14 Mer.