

U. S. Department of Agriculture

FOREST SERVICE

1512

Patrol 215

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 31 W. 5th. Mer.

S ~~40-31~~ Corner common to Sections
340-31, and 34

Corner consists of a Iron Pipe (~~rod~~) in place



State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Apparently set by County Engineer.

Arthur J. Johnson

(Signature)

Semi Skilled Worker.

(Title)

2/1/38

(Date)

This corner lies in center of new county road. No yellow marker but there are two R. P. Station 35 on new road tell at this corner.

Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. 5th Mer.