

U. S. Department of Agriculture

FOREST SERVICE

W.H.

Chippewa

517

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *31 W* *5th* Mer.

N¹/₁₆ Corner common to Sections

26, and *27*

Corner consists of a *2" I.P.* (not) in place

State condition *Good*

Dimensions above ground *16* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Corner*

P. Moore

6/17/37
(Date)

Asst. Dir. F&S
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


0.64
849E

side of

tree *12* inches diameter, on the

Metal Location Poster is on a

Rock Pine



(Make sketch of topography near Corner)

T. WAIN, R. 3100
5th Mer.