

U. S. Department of Agriculture

FOREST SERVICE

P17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *31 W* *5th* Mer.

14 Corner common to Sections

72, and *73*

Corner consists of a *3" clear post* (not) in place

State condition *Good*

Dimensions above ground *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *None*

Diameter *None*

Bearing *None*

Distance *None*

Do you believe this to be a genuine Land Office Corner? *no*

If not, why? _____

Established by CCC crew

P. Mager
(Signature)

12/29/36 (Date) *Asst. Dir. - F 48* (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.33


from which this Corner bears

058 W

side of

tree 10 inches diameter on the

Metal Location Poster is on a *Jack Pine*



(Make sketch of topography near Corner)

Mer.

5th

T. 14 N. R. 31 W.