

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Posted C17

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 5th Mer.
Quarter

Corner common to Sections
3, and 2

Corner consists of a cap. iron pipe (not) in place
State condition good

Dimensions above ground 2 1/2 x 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

None			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species None

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

County Re survey

Dorman J Sutton

(Signature)

Engineer

(Title)

3/30/31

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *N 18° W*

side of *tree*

tree *3* inches diameter, on the *NW* side of *A.S.P.C.*

Metal Location Poster is on a



(Make sketch of topography near Corner)

T141N R31W 5th Mer.