

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

CHIPPENAW NATIONAL FOREST

V 19

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31W 8th Mer.

1/4 Corner common to Sections  
26, and 35

Corner consists of an IRON PIPE (not) in place  
State condition GOOD

Dimensions above ground 12 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? APPARENTLY SET BY

COUNTY ENGINEER

Arthur T. Charles

(Signature)

Leslie H. Shell

(Title)

12/14/27

(Date)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.

Give any further facts which will aid in finding this


----- chains distant.

----- from which this Corner bears

----- side of

----- tree ----- inches diameter, on the

----- Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. Mer. *SA*