

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

519

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 31 W 5th Mer.

C. N. 4⁶ Corner common to Sections 26, and

Corner consists of an iron pipe (not) in place State condition good

Dimensions above ground 2 x 24 inches Sketch grooves, letters, figures, or notches, on proper face or edge. CARDINAL POSITION DIAGONAL POSITION

None			
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species None Diameter Bearing Distance

Do you believe this to be a genuine Land Office Corner?

If not, why? County Resurvey Corner

Dansman J. Sutton

(Signature)

Engineer

(Title)

4/3/35 (Date)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears *West*

side of *tree*

tree *2* inches diameter, on the *West*

Metal Location Poster is on an *Aspen*



(Make sketch of topography near Corner)

Mer.

5th

R. B. W.

T. L. H. N.