

U. S. Department of Agriculture
FOREST SERVICE

N19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31W 5th Mer.

Corner common to Sections

14, and 23Corner consists of a 4" Aspen post (not) in placeState condition GoodDimensions above ground 48" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Approximate locationestablished by C.C.C. crewCarl Steadman

(Signature)

Dec. 23, 1936

(Date)

Const. For.

(Title)

Corner again.

Give any further facts which will aid in finding this

0.07 chains distant.

from which this Corner bears


N 74 E

side of

tree 12 inches diameter, on the

Metal Location Poster is on a

Nor. pine



(Make sketch of topography near Corner)

Mer.

5th

T. 14 N. R. 3 W.