

U. S. Department of Agriculture
FOREST SERVICE

123
7-29-37
[Signature]

X-20

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N. R. 31 W. 5th Mer.

NE 1/4 Corner common to Sections
14, _____, and _____

Corner consists of a 5" (not) in place
State condition Good

Dimensions above ground 48" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

Approximate location

Established by C.C.C. crew

Carl Steadman


(Signature)

Const. For.

(Title)

Dec. 23, 1936
(Date)

Corner again.
 Give any further facts which will aid in finding this
 side of *OH* chains distant.
 from which this Corner bears *N 36° W*
 tree *4* inches diameter, on the
 Metal Location Poster is on a *Jack Pine*



(Make sketch of topography near Corner)

T. L. H. N. R. 31 W.

Mer.

K-20

5 H

U. S. Department of Agriculture
FOREST SERVICE

K20

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 14/N R. 3/W 5th Mer.

NE 1/4 Corner common to Sections
14, _____, _____, and _____

Corner consists of a 5" (not) in place
State condition Good

Dimensions above ground 48" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

Approximate location
established by C.C.C. crew


C. Steadley
(Signature)

Dec 23, 1936
(Date)

Const. For.
(Title)

Metal Location Poster is on a *lock Pine* tree *4* inches diameter, on the side of from which this Corner bears *N 36 W* *0.77* chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. S. 5th Mer.