

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST *Posted D22*

CORNERS OF THE PUBLIC SURVEY  
T. *141 N.* R. *31 W.* S. *5* Mer.  
*Sub. #6* Corner common to Sections

Corner consists of a *Not Found* (not) in place  
State condition

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


<i>SW</i> <i>1/16</i> <i>51</i>			
<i>BT</i>			

Species *N. Pine*  
Diameter *1 1/2*  
Bearing *N.E.*  
Distance *?*

Do you believe this to be a genuine Land Office Corner? *Yes*  
If not, why? \_\_\_\_\_

*Dorman Sutton*  
(Signature)  
*3-12-35* (Date) *Engineer* (Title)  
8-7504

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.  
Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. H. N. R. G. L. W. 5-75 Mer.