

U. S. Department of Agriculture

FOREST SERVICE

*Ref*  
*A 24*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 31 W. 5th Mer.  
E. 1/16

Corner common to Sections  
141-31, and 36-142-31

Corner consists of a 1" IM W/ Brass Cap in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E. 1/16 S. 1	E. 1/16 S. 1		
B. T.	B. T.		

Species R. Pine R. Pine

Diameter 20" 12"

Bearing S 4° W S 29° E

Distance 2.52 ch 2.31 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Arthur T. Johnson*  
Arthur T. Johnson  
(Signature)

2/9/38  
(Date)

Semi Skilled Worker  
(Title)

Corner sets 20 chains West of  
Cross roads just North of Camp R-48.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. 31 W. 5th Mer.