

U. S. Department of Agriculture
FOREST SERVICE

Poste 225

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *140+141* R. *30+31* *5* Mer.

Section Corner common to Sections

31, *36*, *1*, and *6*

Corner consists of a *iron pipe* (~~rod~~) in place

State condition *good*

Dimensions above ground *2x18* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>None</i>			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *None*

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? _____

Ca. Resurvey

Dorman J. Sutton
(Signature)

3/27/35
(Date)

E 19
(Title)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


65 chains distant.

from which this Corner bears N 87° E

side of ~~A~~ tree

tree 12 inches diameter, on the East

Metal Location Poster is on a N Pine



(Make sketch of topography near Corner)

T 1404 LHT R. 304 81 5 Mer.