

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *31* Mer. *W*

Section *25* Corner common to Sections *R 30*

25, *36*, *30*, and *31*

Corner consists of a *cap iron pipe* in place

State condition *good*

Dimensions above ground *2 1/2 x 2 0* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>None</i>			
-------------	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *None*

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Dorman J. Sutton

(Signature)

Engineer

(Title)

3/27/35

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

18

from which this Corner bears

East

side of


stab

two 2 inches diameter, on the

N E

Metal Location Poster is on a

Post of 1/2



(Make sketch of topography near Corner)

T. L. L. N. R. 31 W. 30 N. 5 TH Mer.