

U. S. Department of Agriculture

FOREST SERVICE

Posted J25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *31W* ⁵⁰ *5* Mer.

Sec *5* Corner common to Sections
12, *7*, *18*, and *13*

Corner consists of a *Brass Plate* in place
State condition *OK. S. Diameter*

Dimensions above ground *2 1/2 Dia.* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T 141N R 31W S 5</i>

<i>T 141N R 31W S 5</i>

--

--

<i>BT</i>

<i>BT</i>

--

--

Species *N. Pine Oak*

Diameter *8" 7"*

Bearing *N28°W N39°E*

Distance *70' 200'*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____


[Signature]
(Signature)

ENGINEER

(Title)

3/6/35
(Date)

Metal Location Poster is on a NONE
 tree _____ inches diameter, on the _____
 side of _____
 from which this Corner bears _____
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. L. N. R. #7-W930W 5 Mer.