

U. S. Department of Agriculture
FOREST SERVICE

1923
7-21-37
A25
[Signature]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141-142 R. 30-31 6 Mer.
Section

Corner common to Sections
36, 31, 6, and 1
Corner consists of a 2" iron pipe w/brass cap in place

State condition Good

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	No B. Ts.	

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. E. ALTMAN
(Signature)

Assistant Ranger

9/14/36

(Date)

(Title)

1-48

C.L.R.

66-3.0.

Corner is on west side of N-5 road at intersection with road turning east.

Corner again.

Give any further facts which will aid in finding this

chain distant

5455


from which this Corner bears

1/4 mi of road intersection.

tree 7 inches diameter, on the NE corner

1/4 mi

Metal Location Poster is on a



(Make sketch of topography near Corner)