

## U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

V20-21

## CORNERS OF THE PUBLIC SURVEY

T. 141N R. 31W 5<sup>th</sup> Mer.

Meander Corner common to Sections

, , 26, and 35

Corner consists of a cap iron pipe (not) in place

State condition good

Dimensions above ground 2 1/2 x 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		None	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species Nine

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

County ResurveyDorman J. Sutton

(Signature)

Engineer

(Title)

4/3/35

(Date)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *None*



(Make sketch of topography near Corner)

T. 141N R. 31W Mer. *5-14*