

U. S. Department of Agriculture
FOREST SERVICE

E9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 25W 5th Mer.

Section 5 4 8 Corner common to Sections 9
, , , and

Corner consists of a Cedar Post in place

State condition Poor

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S5	T-142N		S4
	R-25W	S8	S9
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S9			
B.T.			

Species Elm

Diameter Snag

Bearing S36° E

Distance 0.58 Chs

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Arthur H. Jager

Arthur H. Jager

(Signature)


Chief of Party

(Title)

8/26/36

(Date)

(Make sketch of topography in this corner)



Metal Location Poster is on a elm snag
 tree _____ inches diameter, on the North West
 side of Snag
 from which this Corner bears N36°W
0.58 chains distant.

Give any further facts which will aid in finding this
 Corner again.

U. S. Department of Agriculture
FOREST SERVICE

E9

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 25W 5th Mer.

Section

3 4 8 and 9

Corner common to Sections

Corner consists of a Cedar Post (30) in place

State condition Poor

Dimensions above ground 50" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

55	7-142N		
	2-25W		54
50		50	
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

50			
B.T.			

Species Elm
Diameter 3 3/8"
Bearing 93° E
Distance 0.55

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? C. Co

Arthur H. Jager
Arthur H. Jager

(Signature)


Chief of Party

8/26/38

(Date)

(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on an elm snag
 tree _____ inches diameter, on the North West
 side of snag
 from which this Corner bears N52° 7'
0.58 chains distant.

Give any further facts which will aid in finding this
 Corner again.