

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

A-21

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ~~141-142N~~ R. 25W 5th. Mer.

Section 1, 2, (35), and 36  
 Corner common to Sections

Corner consists of a Scribed cedar post in place  
 State condition Good

Dimensions above ground 6 x 6 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

T141N	T141	T141	T142
R25W	R25W	R25W	R25W
S35	S2	S1	S36
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	No B.T.'s		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? C. C. C.

T. H. Williams  
 (Signature)

Jr. Asst. To Tech.  
 (Title)

Aug. 17, 1937  
 (Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.65

from which the Corner bears


N 50° E

side of

Tree

tree 6" inches diameter, on the South

Metal Location Post is on a Spruce



(Make sketch of topography near Corner)

Mer. 7-21

5th

T. 141-142 R. 25N