

U. S. Department of Agriculture

FOREST SERVICE

J-9

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 26 5th. Mer.

section Corner common to Sections 8, 9, 17, and 16

Corner consists of a iron pipe (not) in place

State condition good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

B.T.			
------	--	--	--

Species Pine Diameter 3TP Bearing N13E Distance 42'

Do you believe this to be a genuine Land Office Corner? No.

If not, why? probable county survey

O.G. Q.

(Signature)


Mar. 2, 1935

ENGINEER

(Date)

(Title)

Metal Location: Poster is on a black stump
 tree 28 inches diameter, on the North corner
 side of county road
 from which this Corner bears
 18 chains distant.
 Give any further facts which will aid in finding this
 Corner again.
 Appx. Intersection of tangents at
 middle of road.



(Shows location of topography near Corner)