

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Revised

E-15

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14E R. 26 5 Mer.

1 Corner common to Sections
3, and 10

Corner consists of a stake ~~stone~~ in place


State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species cedar str.

Diameter 1 1/2

Bearing S 10 W

Distance 5 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R. T. Defant
 RAYMOND T. DEFANT
 (Signature)

Jr. Civil Engineer
 (Title)

10/23/40
 (Date)

UNITED STATES GEOLOGICAL SURVEY

WASHINGTON, D. C.

WATER RESOURCES DIVISION

REPORT OF INVESTIGATION

NO. 1

OF THE
UNITED STATES GEOLOGICAL SURVEY
WASHINGTON, D. C.

FROM WHICH THE CENTER BEARS
SIDE OF
INCHES DIAMETER, ON THE
METAL LOCATION POSTER ON A

