

Form 874-0—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

2-19

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 26 S. 5 Mer.

S. 1/2 Corner common to Sections  
25, and 26

Corner consists of a 30 pipe (not) in place  
State condition good

Dimensions above ground flush inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	N	O	N	E	

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No.

If not, why? \_\_\_\_\_

County Corner

R. T. Clefont  
Raymond T. Clefont  
(Signature)

Jr. Civil Engineer  
(Title)

4-10-40  
(Date)


U.S. Department of Agriculture  
FOREST SERVICE

NATIONAL FOREST

CORNER OF THE PUBLIC SURVEY

Give any further facts which will aid in finding the  
corner again.  
Chain distant

Metal Location Poster is on a  
tree inches diameter, on the  
side of  
from which this Corner bears  
South  
North  
Chain distant



(Make sketch of topography near Corner)