

U. S. Department of Agriculture

FOREST SERVICE

V-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 27W 5th Mer.

$\frac{1}{4}$  Corner common to Sections 29, 32, and

Corner consists of a Brass Cap (not) in place

State condition Good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*M. J. Starn*

(Signature)

ASST. FOR. RANGE

(Title)

10/28/59  
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


4.1

from which this Corner bears 178° South

side of this tree on South side of the road

tree 5 inches diameter, on the North

Metal Location Poster is on a Balsam Fir



(Make sketch of topography near Corner)

T. 112N

R. 27W

5th

M. 7