

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

P.  
 58

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 27 W \_\_\_\_\_ 5 Mer.

E 1/4 Corner common to Sections

8, 17, 26, and 35 and 4 (Close to top)  
 Corner consists of a stone post (not) in place


State condition good

Dimensions above ground \_\_\_\_\_ 6 inches

Sketch graves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen

Diameter 14

Bearing N 44° W

Distance 28 LINKS

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

A. Mataya

(Signature)

4-2-35

(Date)

Estimator

(Title)

2. Location of the corner

SECTION OF SECTION

CORNER OF THE SECTION

Corner again:

Give any further facts which will aid in finding this

chain distant.


from which this Corner bears

N 39° W

side of

tree 4 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)